FIRE ESCAPE REPAIRS AND ASSOCIATED WORK AT THE CARDINAL O'CONNELL, GREEN, MOLLOY, MOODY, AND WASHINGTON SCHOOLS

PREPARED FOR
CITY OF LOWELL
375 MERRIMACK STREET
LOWELL, MA 01852

DRAWING NO	<u>TITLE</u>
G100	COVER SHEET
G101	LOCUS PLAN AND SCHOOL ADDRESS
A101	CARDINAL O'CONNELL SCHOOL FIRE ESCAPE PLANS
A102	CARDINAL O'CONNELL SCHOOL FIRE ESCAPE PLANS
A103	GREEN SCHOOL FIRE ESCAPE PLANS
A104	GREEN SCHOOL FIRE ESCAPE PLANS
A105	GREEN SCHOOL FIRE ESCAPE PLANS
A106	MOLLOY SCHOOL FIRE ESCAPE PLANS
A107	MOODY SCHOOL FIRE ESCAPE PLANS
A108	MOODY SCHOOL FIRE ESCAPE PLANS
A109	WASHINGTON SCHOOL NORTH FIRE ESCAPE PLANS
A110	WASHINGTON SCHOOL NORTH FIRE ESCAPE PLANS
A111	WASHINGTON SCHOOL SOUTH FIRE ESCAPE PLANS
A112	WASHINGTON SCHOOL SOUTH FIRE ESCAPE PLANS
A201	CARDINAL O'CONNELL SCHOOL FIRE ESCAPE ELEVATIONS AND DETAIL PHOTOS
A202	GREEN SCHOOL FIRE ESCAPE ELEVATIONS AND DETAIL PHOTOS
A203	MOLLOY SCHOOL FIRE ESCAPE ELEVATIONS AND DETAIL PHOTOS
A204	MOODY SCHOOL FIRE ESCAPE ELEVATIONS AND DETAIL PHOTOS
A205	WASHINGTON SCHOOL NORTH FIRE ESCAPE ELEVATIONS AND DETAIL PHOTOS
A206	WASHINGTON SCHOOL SOUTH FIRE ESCAPE ELEVATIONS AND DETAIL PHOTOS
A501	DETAILS
A502	DETAILS





Engineers and Plant

163 LIBBEY PARKWAY | WEYMOUTH, MA 02189 P 781.335.6465 F 781.335.6467 www.gainc.com

Boston Baltimore Orlando Hartfor

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc.

Convright©2018

FIRE ESCAPE REPAIRS AND ASSOCIATED WORK
MOLLOY MOODY AND WASHINGTON SCHOOLS
LOWELL, MA 01852
OWNER
CITY OF LOWELL ENGINEERING DEPARTMENT
375 MERRIMACK STREET

Ο.	DATE	D	DESCRIPTION		
PROJECT NO.			835300		
CADD FILE			835300 G100		
DESIGNED BY			ACP/AEO		
DRAWN BY			ALP		
CHECKED BY			AEO / SRM		

DRAWING SCALE NOT TO SCALE

GRAPHIC SCALE

12/13/2019

SHEET TITLE

COVER SHEET

G100

CARDINAL O'CONNELL SCHOOL

21 CARTER STREET LOWELL, MA 01852

GREEN SCHOOL

408 MERRIMACK STREET LOWELL, MA 01852

MOLLOY SCHOOL


125 SMITH STREET LOWELL, MA 01852

MOODY SCHOOL

158 ROGERS STREET LOWELL, MA 01851

WASHINGTON SCHOOL

795 WILDER STREET LOWELL, MA 01851



LOCATION MAP NOT TO SCALE



Gale Associates, Inc.

163 LIBBEY PARKWAY | WEYMOUTH, MA 02189

Boston Baltimore Orlando Hartford

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc.

Copyright©2018

Ī	
	FIRE ESCAPE REPAIRS AND ASSOCIATED WORK AT THE CARDINAL O'CONNELL, GREEN,
	LOWELL, MA 01852
	OWNER
	CITY OF LOWELL ENGINEERING DEPARTMENT 375 MERRIMACK STREET

			-
DATE	DESCRIPTION		ВҮ
JECT NO.		835300	
D FILE		835300 G100)
IGNED BY		ACP/AEO	
WN BY		ALP	
CKED BY		AEO / SRM	

DRAWING SCALE NOT TO SCALE


GRAPHIC SCALE


12/13/2019


SHEET TITLE


LOCUS PLAN AND SCHOOL ADDRESS


C1 O1



















NOTE: ALL REPAIR ITEMS MAY NOT BE SHOWN ON THIS SHEET

APPROXIMATE LIMITS OF BITUMINOUS CONCRETE TO BE REMOVED AND REPLACED TO INSTALL

NEW BOLLARDS





EXISTING STAIR AND STRINGER CHANNELS

EXISTING CHANNEL

EXISTING HANDRAILS

EXISTING EGRESS DOOR

EXISTING FIRE ESCAPE BEYOND

BOLLARD AND CAST-IN-PLACE CONCRETE PIER

APPROXIMATE LIMITS OF BITUMINOUS CONCRETE TO BE REMOVED AND REPLACED AS REQUIRED

EXISTING GRATE WALKWAY

TO INSTALL NEW BOLLARDS

SCRAPE, PRIME AND PAINT THE PERIMETER OF THE COLUMN FROM THE COLUMN BASE TO A

CLEAN EXISTING HANDRAIL OF EXISTING PAINT, DUST AND DEBRIS AND WELD A NEW GALVANIZED STEEL ANGLE TO THE HANDRAIL. MECHANICALLY ATTACH THE ANGLE TO THE

MATCH THE EXISTING. (PAINTING FILED SUB-BID REQUIRED) (REFER TO DETAIL 5/A501)

(PAINTING FILED SUB-BID REQUIRED) (REFER TO DETAIL 6/A501 & 12/A502)

DRILL NEW FASTENER HOLE THROUGH STEEL PLATE AND INTO SOLID BRICK MASONRY SUBSTRATE AND INSTALL NEW EXPANSION ANCHOR. PAINT TO MATCH EXISTING COLOR.

NOTE: ALL REPAIR ITEMS MAY NOT BE SHOWN ON THIS SHEET

ADJACENT BRICK MASONRY WALL AND PAINT THE ANGLE AND EXISTING HANDRAIL; COLOR TO

REMOVE AND REPLACE DETERIORATED OR MISSING THROUGH-BOLT; PAINT TO MATCH EXISTING;

INSTALL NEW COLUMN CAP. PROFILE AND COLOR TO MATCH THE ADJACENT EXISTING COLUMN

REMOVE AND REPLACE STAIR TREADS, STRINGERS AND HANDRAILS IN LIKE KIND AND PROVIDE NEW CONCRETE SONOTUBE FOOTINGS AT BASE OF STRINGERS; PAINT TO MATCH EXISTING.

REMOVE DISPLACED ANGLE AND SCRAPE, PRIME AND PAINT STRINGER AND CHANNEL TO MATCH EXISTING COLOR. INSTALL NEW CLIP ANGLE WITH THROUGH-BOLTS. (PAINTING FILED

MINIMUM OF 6'-0" ABOVE THE COLUMN BASE. PAINT COLOR TO MATCH THE EXISTING.

(PAINTING FILED SUB-BID REQUIRED)

install New Column Cap. Profile and CC Caps. (Painting filed Sub-bid Required)

(PAINTING FILED SUB-BID REQUIRED)

SUB-BID REQUIRED)

REMOVE AND REPLACE DETERIORATED ON MISSING # INDICATES UNIT QUANTITY. (PAINTING FILED SUB-BID REQUIRED)

APPLICABLE TO THE PROJECT.

SPECIFICATIONS FOR FASTENER TYPES AND SPACING.

FOR SETUP AND STORAGE OF MATERIALS.

REQUIREMENTS.

THE CONTRACTOR IS CAUTIONED THAT DUE TO BUILDING OCCUPANCY, THE OWNER REQUIRES COMPLIANCE ON

WORK HOURS, SCHEDULING, SET-UP, CLEANUP, PARKING, SECURITY, ETC. REFER TO SPECIFICATIONS FOR OWNER

FOR THE SAKE OF CLARITY, SECUREMENT FASTENERS ARE NOT SHOWN ON THE DETAIL DRAWINGS. REFER TO THE

DETAILS NOT DEPICTED SHALL BE CONSTRUCTED IN A MANNER CONSISTENT WITH THE DETAIL DRAWINGS.

THE CONTRACTOR IS RESPONSIBLE FOR CHECKING AND VERIFYING ALL DIMENSIONS, CONDITIONS, HEIGHTS,

NECESSARY TEMPORARY PROTECTION TO ENSURE THE INTERIOR OF THE BUILDING REMAINS DUST FREE. NO

1. DUE TO THE CONGESTION AROUND THE PROJECT SITE THE CONTRACTOR MUST PROVIDE DETAILED TRAFFIC AND

SCAFFOLDING PLANS TO THE OWNER FOR REVIEW. THE CONTRACTOR WILL ONLY BE ALLOWED THE AREAS SHOWN

10. THE BUILDING SHALL BE MAINTAINED IN A DUST FREE CONDITION. THE CONTRACTOR SHALL PROVIDE ALL

AND/OR INDICATED ON THE DRAWINGS OR NOTED IN THE WRITTEN SPECIFICATIONS - TYPICAL.

DEMOLITION CAN PROCEED UNTIL AN APPROVED TEMPORARY PROTECTION SYSTEM IS IN PLACE.

THE CONTRACTOR SHALL BE RESPONSIBLE FOR REMOVING AND LEGALLY DISPOSING OF ALL MATERIALS LISTED

MATERIAL THICKNESSES, ETC., IN THE FIELD PRIOR TO SUBMITTING THEIR BID AND COMMENCING CONSTRUCTION.



NO. DATE DESCRIPTION PROJECT NO. Washington A100s CADD FILE DESIGNED BY ACP/AEO DRAWN BY ACP/ALP AEO / SRM CHECKED BY 12/13/2019


GALE

Copyright©2018

DRAWING SCALE | AS NOTED GRAPHIC SCALE

SHEET TITLE

WASHINGTON SCHOOL NORTH FIRE ESCAPE PLANS



EXISTING EGRESS DOOR

EXISTING FIRE ESCAPE BEYOND

EXISTING GRATE WALKWAY

REMOVE AND REPLACE DETERIORATED OR MISSING THROUGH—BOLT; PAINT TO MATCH EXISTING; # # INDICATES UNIT QUANTITY. (PAINTING FILED SUB—BID REQUIRED)

INSTALL NEW COLUMN CAP. PROFILE AND COLOR TO MATCH THE ADJACENT EXISTING COLUMN CAPS. (PAINTING FILED SUB—BID REQUIRED)

REMOVE DISPLACED ANGLE AND SCRAPE, PRIME AND PAINT STRINGER AND CHANNEL TO

DRILL NEW FASTENER HOLE THROUGH STEEL PLATE AND INTO SOLID BRICK MASONRY SUBSTRATE AND INSTALL NEW EXPANSION ANCHOR. PAINT TO MATCH EXISTING COLOR.

MATCH EXISTING COLOR. INSTALL NEW CLIP ANGLE WITH THROUGH-BOLTS. (PAINTING FILED

(PAINTING FILDE SUB-BID REQUIRED) (REFER TO DETAIL 6/A501 & 12/A502)

NOTE: ALL REPAIR ITEMS MAY NOT BE SHOWN ON THIS SHEET

SUB-BID REQUIRED)

(PAINTING FILED SUB-BID REQUIRED)

REMOVE AND REPLACE STAIR TREADS, STRINGERS AND HANDRAILS IN LIKE KIND AND PROVIDE NEW CONCRETE SONOTUBE FOOTINGS AT BASE OF STRINGERS; PAINT TO MATCH EXISTING.

DETAILS NOT DEPICTED SHALL BE CONSTRUCTED IN A MANNER CONSISTENT WITH THE DETAIL DRAWINGS.

THE CONTRACTOR IS RESPONSIBLE FOR CHECKING AND VERIFYING ALL DIMENSIONS, CONDITIONS, HEIGHTS,

10. THE BUILDING SHALL BE MAINTAINED IN A DUST FREE CONDITION. THE CONTRACTOR SHALL PROVIDE ALL

NECESSARY TEMPORARY PROTECTION TO ENSURE THE INTERIOR OF THE BUILDING REMAINS DUST FREE. NO

1. DUE TO THE CONGESTION AROUND THE PROJECT SITE THE CONTRACTOR MUST PROVIDE DETAILED TRAFFIC AND

SCAFFOLDING PLANS TO THE OWNER FOR REVIEW. THE CONTRACTOR WILL ONLY BE ALLOWED THE AREAS SHOWN

AND/OR INDICATED ON THE DRAWINGS OR NOTED IN THE WRITTEN SPECIFICATIONS - TYPICAL.

DEMOLITION CAN PROCEED UNTIL AN APPROVED TEMPORARY PROTECTION SYSTEM IS IN PLACE.

FOR SETUP AND STORAGE OF MATERIALS.

. THE CONTRACTOR SHALL BE RESPONSIBLE FOR REMOVING AND LEGALLY DISPOSING OF ALL MATERIALS LISTED

MATERIAL THICKNESSES, ETC., IN THE FIELD PRIOR TO SUBMITTING THEIR BID AND COMMENCING CONSTRUCTION.

GALE

Gale Associates, Inc.

163 LIBBEY PARKWAY | WEYMOUTH, MA 02189 781.335.6465 F 781.335.6467 www.gainc.com


features disclosed are proprietary to Gale Associates, Inc. and shall not be altered o reused in whole or part without the express written permission of Gale Associates, Inc. Copyright©2018

> OCIATED WORK L, GREEN, FON SCHOOLS CAP THE 7, M ES 107

NO. DATE DESCRIPTION PROJECT NO. Washington A100s CADD FILE DESIGNED BY ACP/AEO DRAWN BY ACP/ALP CHECKED BY AEO / SRM 12/13/2019 DRAWING SCALE | AS NOTED GRAPHIC SCALE

SHEET TITLE

WASHINGTON SCHOOL NORTH FIRE ESCAPE PLANS



GENERAL NOTES

- THE INFORMATION SHOWN ON THIS DRAWING HAS BEEN COMPILED FROM VARIOUS SOURCES, AND MAY NOT REFLECT THE ACTUAL CONDITIONS AT THE TIME OF CONSTRUCTION
- HATCH PATTERNS ARE FOR REPRESENTATION ONLY AND SHOULD NOT BE USED AS A MEANS FOR QUANTIFYING.
- DISCREPANCIES NOTED BY THE CONTRACTOR IN THE DRAWINGS OR SPECIFICATIONS MUST BE BROUGHT TO THE OWNER'S ATTENTION PRIOR TO BID SUBMISSION.
- ALL ITEMS OF CONSTRUCTION SHALL BE IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS APPLICABLE TO THE PROJECT.
- THE CONTRACTOR IS CAUTIONED THAT DUE TO BUILDING OCCUPANCY, THE OWNER REQUIRES COMPLIANCE ON WORK HOURS, SCHEDULING, SET-UP, CLEANUP, PARKING, SECURITY, ETC. REFER TO SPECIFICATIONS FOR OWNER REQUIREMENTS.
- FOR THE SAKE OF CLARITY, SECUREMENT FASTENERS ARE NOT SHOWN ON THE DETAIL DRAWINGS. REFER TO THE SPECIFICATIONS FOR FASTENER TYPES AND SPACING.
- DETAILS NOT DEPICTED SHALL BE CONSTRUCTED IN A MANNER CONSISTENT WITH THE DETAIL DRAWINGS.
- THE CONTRACTOR SHALL BE RESPONSIBLE FOR REMOVING AND LEGALLY DISPOSING OF ALL MATERIALS LISTED AND/OR INDICATED ON THE DRAWINGS OR NOTED IN THE WRITTEN SPECIFICATIONS - TYPICAL.
- THE CONTRACTOR IS RESPONSIBLE FOR CHECKING AND VERIFYING ALL DIMENSIONS, CONDITIONS, HEIGHTS, MATERIAL THICKNESSES, ETC., IN THE FIELD PRIOR TO SUBMITTING THEIR BID AND COMMENCING CONSTRUCTION.
- . THE BUILDING SHALL BE MAINTAINED IN A DUST FREE CONDITION. THE CONTRACTOR SHALL PROVIDE ALL NECESSARY TEMPORARY PROTECTION TO ENSURE THE INTERIOR OF THE BUILDING REMAINS DUST FREE. NO DEMOLITION CAN PROCEED UNTIL AN APPROVED TEMPORARY PROTECTION SYSTEM IS IN PLACE.
- . DUE TO THE CONGESTION AROUND THE PROJECT SITE THE CONTRACTOR MUST PROVIDE DETAILED TRAFFIC AND SCAFFOLDING PLANS TO THE OWNER FOR REVIEW. THE CONTRACTOR WILL ONLY BE ALLOWED THE AREAS SHOWN FOR SETUP AND STORAGE OF MATERIALS.

LEGEND EXISTING BRICK MASONRY WALL APPROXIMATE LIMITS OF BITUMINOUS CONCRETE TO EXISTING EGRESS DOOR BE REMOVED AND REPLACED AS REQUIRED EXISTING CONCRETE FOOTING WITH TO INSTALL NEW BOLLARDS COLUMN TOO EXISTING COLUMN EXISTING GRATE WALKWAY CAST-IN-PLACE EXISTING STAIR AND STRINGER SONOTUBE FOOTING CHANNELS EXISTING CHANNEL STAIR AND STRINGER CHANNELS BOLLARD AND CAST-IN-PLACE CONCRETE PIER EXISTING HANDRAILS EXISTING FIRE ESCAPE BEYOND

REPAIR NOTES AND LEGEND

- DM DETERIORATED MORTAR JOINT TO BE CUT AND POINTED; # REMOVE AND REPLACE DETERIORATED OR MISSING # INDICATES SQUARE FEET (REFER TO DETAIL 1/A501)
- CRACKED CONCRETE TO BE REPAIRED; # INDICATES LINEAR FEET D INDICATES CRACKS GREATER THAN 1/4" IN WIDTH (REFER TO DETAIL 2/A501)
- S INDICATES CRACKS LESS THAN 1/4" IN WIDTH (REFER TO DETAIL 3/A501)
- SC SPALLED CONCRETE TO BE REPAIRED; # INDICATES SQUARE FEET (REFER TO DETAIL 4/A501)
- SCRAPE, PRIME AND PAINT THE PERIMETER OF THE COLUMN FROM THE COLUMN BASE TO A MINIMUM OF 6'-0" ABOVE THE FILED SUB-BID REQUIRED)
- CLEAN EXISTING HANDRAIL OF EXISTING PAINT, DUST AND DEBRIS AND WELD A NEW GALVANIZED STEEL ANGLE TO THE HANDRAIL. MECHANICALLY ATTACH THE ANGLE TO THE ADJACENT BRICK MASONRY WALL AND PAINT THE ANGLE AND EXISTING HANDRAIL; COLOR TO MATCH THE EXISTING. (PAINTING FILED SUB-BID **REQUIRED)** (REFER TO DETAIL 5/A501)

- (3) THROUGH-BOLT; PAINT TO MATCH EXISTING; # INDICATES UNIT #QUANTITY. (PAINTING FILED SUB-BID REQUIRED)
- INSTALL NEW COLUMN CAP. PROFILE AND COLOR TO MATCH THE ADJACENT EXISTING COLUMN CAPS. (PAINTING FILED SUB-BID
- REMOVE AND REPLACE STAIR TREADS, STRINGERS AND HANDRAILS IN LIKE KIND AND PROVIDE NEW CONCRETE SONOTUBE FOOTINGS AT BASE OF STRINGERS; PAINT TO MATCH EXISTING. (PAINTING FILED SUB-BID REQUIRED) (REFER TO DETAIL 6/A501 & 12/A502)
- REMOVE DISPLACED ANGLE AND SCRAPE, PRIME AND PAINT COLUMN BASE. PAINT COLOR TO MATCH THE EXISTING. (PAINTING 6) STRINGER AND CHANNEL TO MATCH EXISTING COLOR. INSTALL NEW CLIP ANGLE WITH THROUGH-BOLTS. (PAINTING FILED SUB-BID REQUIRED)
 - DRILL NEW FASTENER HOLE THROUGH STEEL PLATE AND INTO SOLID BRICK MASONRY SUBSTRATE AND INSTALL NEW EXPANSION ANCHOR. PAINT TO MATCH EXISTING COLOR. (PAINTING FILED SUB-BID REQUIRED)

NOTE: ALL REPAIR ITEMS MAY NOT BE SHOWN ON THIS SHEET

KEY PLAN



GALE

163 LIBBEY PARKWAY | WEYMOUTH, MA 02189 P 781.335.6465 F 781.335.6467 www.gainc.com

ston Baltimore Orlando Hartford

features disclosed are proprietary to Gale Associates, Inc. and shall not be altered o reused in whole or part without the express written permission of Gale Associates, Inc. Copyright©2018


TED WORK SREEN, SCHOOLS , A, JO ON G, G, CARDINAL ODY, AND LOWELL, I CAP THE ', M ES AT LOY

NO. DATE DESCRIPTION PROJECT NO. CADD FILE Washington A100s DESIGNED BY ACP/AEO

DRAWN BY ALP/ACP AEO / SRM CHECKED BY 12/13/2019 DRAWING SCALE | AS NOTED GRAPHIC SCALE

SHEET TITLE

WASHIINGTON SCHOOL SOUTH FIRE ESCAPE PLANS



GENERAL NOTES

THE INFORMATION SHOWN ON THIS DRAWING HAS BEEN COMPILED FROM VARIOUS SOURCES, AND MAY NOT REFLECT THE ACTUAL CONDITIONS AT THE TIME OF CONSTRUCTION.

HATCH PATTERNS ARE FOR REPRESENTATION ONLY AND SHOULD NOT BE USED AS A MEANS FOR QUANTIFYING.

- DISCREPANCIES NOTED BY THE CONTRACTOR IN THE DRAWINGS OR SPECIFICATIONS MUST BE BROUGHT TO THE OWNER'S ATTENTION PRIOR TO BID SUBMISSION.
- 4. ALL ITEMS OF CONSTRUCTION SHALL BE IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS APPLICABLE TO THE PROJECT.
- THE CONTRACTOR IS CAUTIONED THAT DUE TO BUILDING OCCUPANCY, THE OWNER REQUIRES COMPLIANCE ON WORK HOURS, SCHEDULING, SET-UP, CLEANUP, PARKING, SECURITY, ETC. REFER TO SPECIFICATIONS FOR OWNER REQUIREMENTS.
- FOR THE SAKE OF CLARITY, SECUREMENT FASTENERS ARE NOT SHOWN ON THE DETAIL DRAWINGS. REFER TO THE SPECIFICATIONS FOR FASTENER TYPES AND SPACING.
- DETAILS NOT DEPICTED SHALL BE CONSTRUCTED IN A MANNER CONSISTENT WITH THE DETAIL DRAWINGS.
- 8. THE CONTRACTOR SHALL BE RESPONSIBLE FOR REMOVING AND LEGALLY DISPOSING OF ALL MATERIALS LISTED AND/OR INDICATED ON THE DRAWINGS OR NOTED IN THE WRITTEN SPECIFICATIONS - TYPICAL.
- 9. THE CONTRACTOR IS RESPONSIBLE FOR CHECKING AND VERIFYING ALL DIMENSIONS, CONDITIONS, HEIGHTS, MATERIAL THICKNESSES, ETC., IN THE FIELD PRIOR TO SUBMITTING THEIR BID AND COMMENCING CONSTRUCTION.
- 10. THE BUILDING SHALL BE MAINTAINED IN A DUST FREE CONDITION. THE CONTRACTOR SHALL PROVIDE ALL NECESSARY TEMPORARY PROTECTION TO ENSURE THE INTERIOR OF THE BUILDING REMAINS DUST FREE. NO DEMOLITION CAN PROCEED UNTIL AN APPROVED TEMPORARY PROTECTION SYSTEM IS IN PLACE.
- 11. DUE TO THE CONGESTION AROUND THE PROJECT SITE THE CONTRACTOR MUST PROVIDE DETAILED TRAFFIC AND SCAFFOLDING PLANS TO THE OWNER FOR REVIEW. THE CONTRACTOR WILL ONLY BE ALLOWED THE AREAS SHOWN FOR SETUP AND STORAGE OF MATERIALS.

features disclosed are proprietary to Gale Associates, Inc. and shall not be altered o reused in whole or part without the express written permission of Gale Associates, Inc. Copyright©2018

AND ASSOCIATED WORK O'CONNELL, GREEN, WASHINGTON SCHOOLS MA 01852

CARDINAL ODY, AND LOWELL, I

CAP THE 7, M


ES 107

163 LIBBEY PARKWAY | WEYMOUTH, MA 02189

P 781.335.6465 F 781.335.6467 www.gainc.com

oston Baltimore Orlando Hartford

GALE



REPAIR NOTES AND LEGEND

DM DETERIORATED MORTAR JOINT TO BE CUT AND POINTED; # REMOVE AND REPLACE DETERIORATED OR MISSING # INDICATES SQUARE FEET (REFER TO DETAIL 1/A501)

CRACKED CONCRETE TO BE REPAIRED; # INDICATES LINEAR FEET D INDICATES CRACKS GREATER THAN 1/4" IN WIDTH (REFER TO DETAIL 2/A501)

- S INDICATES CRACKS LESS THAN 1/4" IN WIDTH (REFER TO DETAIL 3/A501)
- SC SPALLED CONCRETE TO BE REPAIRED; # INDICATES SQUARE FEET # I(REFER TO DETAIL 4/A501)SCRAPE, PRIME AND PAINT THE PERIMETER OF THE COLUMN
- FROM THE COLUMN BASE TO A MINIMUM OF 6'-0" ABOVE THE COLUMN BASE. PAINT COLOR TO MATCH THE EXISTING. (PAINTING FILED SUB-BID REQUIRED)
- CLEAN EXISTING HANDRAIL OF EXISTING PAINT, DUST AND DEBRIS AND WELD A NEW GALVANIZED STEEL ANGLE TO THE HANDRAIL. MECHANICALLY ATTACH THE ANGLE TO THE ADJACENT BRICK MASONRY WALL AND PAINT THE ANGLE AND EXISTING HANDRAIL; COLOR TO MATCH THE EXISTING. (PAINTING FILED SUB-BID **REQUIRED)** (REFER TO DETAIL 5/A501)

- THROUGH-BOLT; PAINT TO MATCH EXISTING; # INDICATES UNIT # QUANTITY. (PAINTING FILED SUB-BID REQUIRED)
- INSTALL NEW COLUMN CAP. PROFILE AND COLOR TO MATCH THE ADJACENT EXISTING COLUMN CAPS. (PAINTING FILED SUB-BID
- REMOVE AND REPLACE STAIR TREADS, STRINGERS AND HANDRAILS IN LIKE KIND AND PROVIDE NEW CONCRETE SONOTUBE FOOTINGS AT BASE OF STRINGERS; PAINT TO MATCH EXISTING. (PAINTING FILED SUB-BID REQUIRED) (REFER TO DETAIL 6/A501 & 12/A502)
- REMOVE DISPLACED ANGLE AND SCRAPE, PRIME AND PAINT STRINGER AND CHANNEL TO MATCH EXISTING COLOR. INSTALL NEW CUR ANGLE WITH THROUGH BOLTO. NEW CLIP ANGLE WITH THROUGH—BOLTS. (PAINTING FILED SUB-BID REQUIRED)
- DRILL NEW FASTENER HOLE THROUGH STEEL PLATE AND INTO SOLID BRICK MASONRY SUBSTRATE AND INSTALL NEW EXPANSION ANCHOR. PAINT TO MATCH EXISTING COLOR. (PAINTING FILED SUB-BID REQUIRED)

NOTE: ALL REPAIR ITEMS MAY NOT BE SHOWN ON THIS SHEET

KEY PLAN



NO. DATE DESCRIPTION 835388 PROJECT NO. Washington A100s CADD FILE DESIGNED BY ACP/AEO DRAWN BY ALP/ACP CHECKED BY AEO / SRM 12/13/2019 DRAWING SCALE | AS NOTED

SHEET TITLE

GRAPHIC SCALE

WASHINGTON SCHOOL SOUTH FIRE ESCAPE PLANS




TYPICAL RUSTING




DETERIORATED BRICK AND MORTAR AT PENETRATION SCALE: NOT TO SCALE





THIRD FLOOR LANDING



DISPLACED EXPANSION BOLT

GALE

Gale Associates, Inc.

63 LIBBEY PARKWAY | WEYMOUTH, MA 02189

ton Baltimore Orlando Hartford

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc.

Copyright©2018

OCIATED WORK L, GREEN, TON SCHOOLS MOL

NO. DATE DESCRIPTION 835300 835300 Cardinal PROJECT NO. A200s CADD FILE ACP / AEO DESIGNED BY DRAWN BY CHECKED BY AEO / SRM 12/13/2019 DRAWING SCALE NOT TO SCALE GRAPHIC SCALE

SHEET TITLE

CARDINAL O'CONNELL SCHOOL FIRE ESCAPE ELEVATIONS AND DETAIL PHOTOS

DRAWING NO.

A201

SCRAPE, PRIME AND PAINT 100% OF THE FIRE ESCAPE. PAINT COLOR BE APPROVED BY OWNER. (PAINTING FILED SUB-BID REQUIRED)

REMOVE AND REPLACE DETERIORATED OR MISSING THROUGH—BOLT, PAINT TO MATCH EXISTING; # INDICATES UNIT QUANTITY. (PAINTING FILED SUB—BID REQUIRED)

CLEAN EXISTING HANDRAIL OF EXISTING PAINT, DUST AND DEBRIS AND WELD A NEW GALVANIZED STEEL ANGLE TO HANDRAIL. MECHANICALLY ATTACH THE ANGLE TO THE ADJACENT BRICK MASONRY WALL AND PAINT THE ANGLE AND EXISTING HANDRAIL; COLOR TO MATCH THE EXISTING. (REFER TO DETAIL 5/A501) (PAINTING FILED SUB-BID REQUIRED)

REMOVE AND REPLACE MISSING OR DISPLACED EXPANSION BOLT AND PAINT TO MATCH

EXISTING. (PAINTING FILED SUB-BID REQUIRED)

DRILL TWO (2) NEW FASTENER HOLES THROUGH RAILING BASE PLATE AND CHANNEL. INSTALL THROUGH BOLTS TO SECURE LANDING GRATE AND PAINT TO MATCH EXISTING. (PAINTING FILED CLUB BIG BEST PERSONNEL) SUB-BID REQUIRED)

DRILL NEW FASTENER HOLE THROUGH STEEL PLATE AND INTO SOLID BRICK MASONRY SUBSTRATE. INSTALL NEW EXPANSION ANCHOR AND PAINT; COLOR TO BE APPROVED BY OWNER. (PAINTING FILED SUB-BID REQUIRED)

DRILL NEW FASTENER HOLE INTO CONCRETE FOOTING, INSTALL NEW EXPANSION ANCHOR AND PAINT; COLOR TO BE APPROVED BY OWNER. **(PAINTING FILED SUB—BID REQUIRED)**

REMOVE AND REPLACE HANDRAIL IN LIKE KIND. SCRAPE EXISTING PAINT AND CLEAN DEBRIS
FROM EXISTING STRINGER CHANNEL. WELD NEW HANDRAIL POSTS TO PREPARED EXISTING
STRINGER CHANNEL AND PAINT NEW HANDRAIL AND PREPARED PORTIONS TO EXISTING STRINGER CHANNEL TO MATCH THE EXISTING. (PAINTING FILED SUB-BID REQUIRED)




TYPICAL RUSTING
SCALE: NOT TO SCALE

DETERIORATED MORTAR


SCALE: NOT TO SCALE

GREEN FIRE ESCAPE












8 RUSTING EXFOLIATION AT PLATE
SCALE: NOT TO SCALE

REPAIR NOTES AND LEGEND

- DM DETERIORATED MORTAR JOINT TO BE CUT AND POINTED; # INDICATES SQUARE FEET. (REFER TO DETAIL 1/A501)
- REMOVE AND REPLACE DETERIORATED OR MISSING THROUGH-BOLT, PAINT TO MATCH EXISTING; # INDICATES UNIT QUANTITY
- REMOVE AND REPLACE MISSING OR DISPLACED EXPANSION BOLT AND PAINT TO MATCH EXISTING. (PAINTING FILED SUB-BID REQUIRED)
- SCRAPE, PRIME AND PAINT 100% OF THE FIRE ESCAPE. PAINT COLOR TO BE AS APPROVED BY THE OWNER. (PAINTING FILED SUB-BID REQUIRED)
- REMOVE EXISTING CLIP ANGLES. SCRAPE, PRIME AND PAINT THE ADJACENT STEEL AND INSTALL NEW CLIP ANGLES AND THROUGH BOLTS TO MATCH THE EXISTING. PAINT NEW STEEL ONCE WORK IS COMPLETE, COLOR TO BE AS APPROVED BY THE OWNER. (PAINTING FILED SUB—BID REQUIRED)
- REMOVE AND REPLACE DAMAGE STAIR TREAD IN LIKE KIND. PAINT COLOR TO BE AS APPROVED BY OWNER. (PAINTING FILED SUB-BID REQUIRED)
- CUT AND REMOVE APPROXIMATELY THREE INCHES (3") OF THE CORNER EXTENT FROM THE CHANNEL. CLEAN EXPOSED SURFACES OF ALL RUST, PRIME AND PAINT. INSTALL NEW REINFORCING PLATE AND THROUGH BOLTS AS SHOWN IN DETAIL 7/A502 (PAINTING FILED SUB-BID REQUIRED)
- REMOVE AND REPLACE DETERIORATED OR MISSING J-BOLTS IN LIKE KIND.
 PAINT COLOR TO BE AS APPROVED BY OWNER; # INDICATES UNIT QUANTITY.
 (PAINTING FILED SUB-BID REQUIRED)

NOTE: ALL REPAIR ITEMS MAY NOT BE SHOWN ON THIS SHEET

KEY PLAN



OCIATED WORK L, GREEN, TON SCHOOLS

GALE

163 LIBBEY PARKWAY | WEYMOUTH, MA 02189 P 781.335.6465 F 781.335.6467 www.gainc.com

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express

written permission of Gale Associates, Inc. Copyright©2018

ston Baltimore Orlando Hartford

Gale Associates, Inc.

•	·				
NO.	DATE	D	DESCRIPTION		
PROJECT NO.			835300 835300 Gree	n	
CADD FILE			A200s		
DESIGNED BY			ACP / AEO		
DRAWN BY			ALP		
CHECKED BY			AEO / SRM		
DATE			12/13/2019		
DRAWING SCALE			NOT TO SCAL	E.	
	CRAPHIC SCALE				

GRAPHIC SCALE

SHEET TITLE

GREEN SCHOOL FIRE ESCAPE ELEVATIONS AND DETAIL PHOTOS

DRAWING NO.

A202





9 STAIR TREAD DAMAGE
SCALE: NOT TO SCALE


MOLLOY FIRE ESCAPE

SHEARED OR DETERIORATED BOLTS



THROUGH BOLTS


MISSING OR DETERIORATED



RUSTING EXFOLIATION

SCALE: NOT TO SCALE

5 DETERIORATED BRICK
SCALE: NOT TO SCALE



DETERIORATED OR MISSING BOLTS AT TREADS SCALE: NOT TO SCALE

GALE

63 LIBBEY PARKWAY | WEYMOUTH, MA 0218

ston Baltimore Orlando Hartford

CIATED WORK L, GREEN, TON SCHOOLS

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc.

Copyright©2018

DESCRIPTION NO. DATE 835300 835300 Molloy PROJECT NO. A200s CADD FILE DESIGNED BY ACP / AEO DRAWN BY AEO / SRM CHECKED BY 12/13/2019 DRAWING SCALE NOT TO SCALE

GRAPHIC SCALE

SHEET TITLE

MOLLOY SCHOOL FIRE ESCAPE ELEVATIONS AND DETAIL PHOTOS

DRAWING NO.

A203


REPAIR NOTES AND LEGEND

OVERALL PHOTO

- DM DETERIORATED MORTAR JOINT TO BE CUT AND POINTED; # INDICATES SQUARE FEET. (REFER TO DETAIL 1/A501)
- REMOVE AND REPLACE DETERIORATED OR MISSING THROUGH—BOLT, PAINT TO MATCH EXISTING; # INDICATES UNIT QUANTITY. (PAINTING FILED SUB—BID REQUIRED)
- CLEAN EXISTING HANDRAIL OF EXISTING PAINT, DUST AND DEBRIS AND WELD A NEW GALVANIZED STEEL ANGLE TO HANDRAIL. MECHANICALLY ATTACH THE ANGLE TO THE ADJACENT BRICK MASONRY WALL AND PAINT THE ANGLE AND EXISTING HANDRAIL; COLOR TO MATCH THE EXISTING. (REFER TO DETAIL 5/A501) (PAINTING FILED SUB-BID REQUIRED)
- DRILL NEW FASTENER HOLE THROUGH STEEL PLATE AND INTO SOLID BRICK MASONRY SUBSTRATE. INSTALL NEW EXPANSION ANCHOR AND PAINT; COLOR TO BE APPROVED BY OWNER. (PAINTING FILED SUB-BID REQUIRED)
- SCRAPE, PRIME AND PAINT 100% OF THE FIRE ESCAPE. PAINT COLOR TO BE AS APPROVED BY THE OWNER. (PAINTING FILED SUB—BID REQUIRED)







SITE PLAN



IATED WORK GREEN, N SCHOOLS


ESCAPI AT THE LOY, MO

163 LIBBEY PARKWAY | WEYMOUTH, MA 02189 P 781.335.6465 F 781.335.6467 www.gainc.com

GALE

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc. Copyright©2018

SECOND LANDING GRATING



BRACKET SUPPORT ANGLES




MISSING ANCHOR BOLT SCALE: NOT TO SCALE



REPAIR NOTES AND LEGEND

- DM DETERIORATED MORTAR JOINT TO BE CUT AND POINTED; # INDICATES SQUARE FEET (REFER TO DETAIL 1/A501)
- CCC CCC D INDICATES CRACKS GREATER THAN 1/4" IN WIDTH (REFER TO DETAIL 2/A501) S INDICATES CRACKS LESS THAN 1/4" IN WIDTH (REFER TO DETAIL 3/A501)
- SC SPALLED CONCRETE TO BE REPAIRED; # INDICATES SQUARE FEET # (REFER TO DETAIL 4/A501)
- REMOVE AND REPLACE DETERIORATED OR MISSING THROUGH—BOLT AND PAINT;

 COLOR TO BE APPROVED BY OWNER. # INDICATES UNIT QUANTITY. (PAINTING FILED) SUB-BID REQUIRED)
- DRILL NEW FASTENER HOLE THROUGH STEEL PLATE AND INTO SOLID BRICK MASONRY SUBSTRATE, INSTALL NEW EXPANSION ANCHOR AND PAINT; COLOR TO BE APPROVED BY OWNER. (PAINTING FILED SUB-BID REQUIRED)
- DRILL NEW FASTENER HOLE INTO CONCRETE FOOTING, INSTALL NEW EXPANSION ANCHOR AND PAINT; COLOR TO BE APPROVED BY OWNER. (PAINTING FILED SUB-BID
- REMOVE AND REPLACE EXISTING LANDING GRATING IN LIKE KIND. PAINT NEW LANDING GRATING; COLOR TO BE APPROVED BY OWNER. (PAINTING FILED SUB—BID REQUIRED)



NOTE: ALL REPAIR ITEMS MAY NOT BE SHOWN ON THIS SHEET

GRAPHIC SCALE

SHEET TITLE

DESCRIPTION

A200s

835300 835300 Moody


ACP / AEO


AEO / SRM

12/13/2019


MOODY SCHOOL FIRE ESCAPE ELEVATION AND DETAIL PHOTOS

A204















CONCRETE FOOTING SCALE: NOT TO SCALE



RUST AT COLUMN SCALE: NOT TO SCALE



HANDRAIL EMBEDMENT SCALE: NOT TO SCALE

REPAIR NOTES AND LEGEND

- DM DETERIORATED MORTAR JOINT TO BE CUT AND POINTED; # INDICATES SQUARE FEET (REFER TO DETAIL 1/A501)
- CRACKED CONCRETE TO BE REPAIRED; # INDICATES LINEAR FEET
 D INDICATES CRACKS GREATER THAN 1/4" IN WIDTH (REFER TO DETAIL 2/A501)
 S INDICATES CRACKS LESS THAN 1/4" IN WIDTH (REFER TO DETAIL 3/A501)
- SC SPALLED CONCRETE TO BE REPAIRED; # INDICATES SQUARE FEET (REFER TO DETAIL # **/** 4/A501)
- SCRAPE, PRIME AND PAINT THE PERIMETER OF THE COLUMN FROM THE COLUMN BASE TO A MINIMUM OF 6'-0" ABOVE THE COLUMN BASE. PAINT COLOR TO MATCH THE EXISTING. (PAINTING FILED SUB-BID REQUIRED)
- CLEAN EXISTING HANDRAIL OF EXISTING PAINT, DUST AND DEBRIS AND WELD A NEW GALVANIZED STEEL ANGLE TO THE HANDRAIL. MECHANICALLY ATTACH THE ANGLE TO THE ADJACENT BRICK MASONRY WALL AND PAINT THE ANGLE AND EXISTING HANDRAIL; COLOR TO MATCH THE EXISTING. (PAINTING FILED SUB-BID REQUIRED) (REFER TO DETAIL 5/A501)
- REMOVE AND REPLACE DETERIORATED OR MISSING THROUGH-BOLT; PAINT TO MATCH REMOVE AND REPLACE DETERIORATED OR MISSING THROUGH—BOLT; PAINT TO EXISTING; # INDICATES UNIT QUANTITY. (PAINTING FILED SUB—BID REQUIRED)
- INSTALL NEW COLUMN CAP. PROFILE AND COLOR TO MATCH THE ADJACENT EXISTING COLUMN CAPS. (PAINTING FILED SUB-BID REQUIRED)
- REMOVE AND REPLACE STAIR TREADS AND STRINGERS IN LIKE KIND AND PROVIDE NEW CONCRETE SONOTUBE FOOTINGS AT BASE OF STRINGERS; PAINT TO MATCH EXISTING. (PAINTING FILED SUB-BID REQUIRED) (REFER TO DETAIL 6/A501 AND 12/A502)
- REMOVE DISPLACED ANGLE AND SCRAPE, PRIME AND PAINT STRINGER AND CHANNEL TO MATCH EXISTING COLOR. INSTALL NEW CLIP ANGLE WITH THROUGH—BOLTS. (PAINTING FILED SUB_RID REQUIRED) SUB-BID REQUIRED)
- DRILL NEW FASTENER HOLE THROUGH STEEL PLATE AND INTO SOLID BRICK MASONRY SUBSTRATE AND INSTALL NEW EXPANSION ANCHOR. PAINT TO MATCH EXISTING COLOR. (PAINTING FILED SUB-BID REQUIRED)

NOTE: ALL REPAIR ITEMS MAY NOT BE SHOWN ON THIS SHEET

KEY PLAN



	NO.	DATE	ESCRIPTION	BY
	PROJECT NO.		835388	
	CADD FILE		Washington A	\200s
	DESIGNED BY		ACP/AEO	
	DRAWN BY		ACP/ALP	
	CHECKED BY		AEO / SRM	
	DAT	E	12/13/2019	

GALE

163 LIBBEY PARKWAY | WEYMOUTH, MA 02189 □ 781.335.6465 □ 781.335.6467 www.gainc.com

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc. Copyright©2018


CIATED WORK GREEN, ON SCHOOLS

ESCAPI AT THE LOY, M(

DRAWING SCALE NOT TO SCALE GRAPHIC SCALE

SHEET TITLE


WASHINGTON SCHOOL NORTH FIRE ESCAPE ELEVATIONS AND DETAIL PHOTOS








SCALE: NOT TO SCALE



6 3" COLUMN BASE
SCALE: NOT TO SCALE

DAMAGED STAIR



7 MISSING COLUMN CAP
SCALE: NOT TO SCALE



4 DISPLACED ANGLE

SCALE: NOT TO SCALE

REPAIR NOTES AND LEGEND

- DETERIORATED MORTAR JOINT TO BE CUT AND POINTED; # INDICATES SQUARE FEET (REFER TO DETAIL 1/A501)
- CRACKED CONCRETE TO BE REPAIRED; # INDICATES LINEAR FEET
 D INDICATES CRACKS GREATER THAN 1/4" IN WIDTH (REFER TO DETAIL 2/A501)
 S INDICATES CRACKS LESS THAN 1/4" IN WIDTH (REFER TO DETAIL 3/A501)
- SPALLED CONCRETE TO BE REPAIRED; # INDICATES SQUARE FEET (REFER TO DETAIL 4/A501)
- SCRAPE, PRIME AND PAINT THE PERIMETER OF THE COLUMN FROM THE COLUMN BASE TO A MINIMUM OF 6'-0" ABOVE THE COLUMN BASE. PAINT COLOR TO MATCH THE EXISTING. (PAINTING FILED SUB-BID REQUIRED)
- CLEAN EXISTING HANDRAIL OF EXISTING PAINT, DUST AND DEBRIS AND WELD A NEW GALVANIZED STEEL ANGLE TO THE HANDRAIL. MECHANICALLY ATTACH THE ANGLE TO THE ADJACENT BRICK MASONRY WALL AND PAINT THE ANGLE AND EXISTING HANDRAIL; COLOR TO MATCH THE EXISTING. (PAINTING FILED SUB—BID REQUIRED) (REFER TO DETAIL 5/A501)
- REMOVE AND REPLACE DETERIORATED OR MISSING THROUGH-BOLT; PAINT TO MATCH EXISTING; # INDICATES UNIT QUANTITY. (PAINTING FILED SUB-BID REQUIRED)
- INSTALL NEW COLUMN CAP. PROFILE AND COLOR TO MATCH THE ADJACENT EXISTING COLUMN CAPS. (PAINTING FILED SUB-BID REQUIRED)
- REMOVE AND REPLACE STAIR TREADS AND STRINGERS IN LIKE KIND AND PROVIDE NEW CONCRETE SONOTUBE FOOTINGS AT BASE OF STRINGERS; PAINT TO MATCH EXISTING. (PAINTING FILE SUB-BID REQUIRED) (REFER TO DETAIL 6/A501 AND 12/A502)
- REMOVE DISPLACED ANGLE AND SCRAPE, PRIME AND PAINT STRINGER AND CHANNEL TO MATCH EXISTING COLOR. INSTALL NEW CLIP ANGLE WITH THROUGH—BOLTS. (PAINTING FILED SUB—BID REQUIRED)
- DRILL NEW FASTENER HOLE THROUGH STEEL PLATE AND INTO SOLID BRICK MASONRY SUBSTRATE AND INSTALL NEW EXPANSION ANCHOR. PAINT TO MATCH EXISTING COLOR. (PAINTING FILED SUB-BID REQUIRED)

NOTE: ALL REPAIR ITEMS MAY NOT BE SHOWN ON THIS SHEET

KEY PLAN



GALE

Gale Associates, Inc.

400 LIDDEY BARKANAY IMEYAOLE

163 LIBBEY PARKWAY | WEYMOUTH, MA 02189 P 781.335.6465 F 781.335.6467 www.gainc.com

This drawing and the design and construction features disclosed are proprietary to Gale Associates, Inc. and shall not be altered or reused in whole or part without the express written permission of Gale Associates, Inc. Copyright@2018

ESCAPE REPAIRS AND ASSOCIATED WORK
AT THE CARDINAL O'CONNELL, GREEN,
LOY, MOODY, AND WASHINGTON SCHOOLS
LOWELL, MA 01852
CITY OF LOWELL ENGINEERING DEPARTMENT
375 MFRRIMACK STRFT

NO. DATE DESCRIPTION BY

PROJECT NO. 835300

CADD FILE Washington A200s

DESIGNED BY ACP/AEO

DRAWN BY ACP

CHECKED BY AEO / SRM

DATE 12/13/2019

DRAWING SCALE NOT TO SCALE

GRAPHIC SCALE

SHEET TITLE

WASHINGTON
SCHOOL SOUTH
FIRE ESCAPE
ELEVATIOINS AND
DETAIL PHOTOS

A206

